

VEHICLE INSPECTION REPORT

YC72FBN

Renault Trafic LL30 BLUEDCI 130PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 30/09/2022

Year 2022

Mileage 60,184 Miles Not Warranted

Fuel Type Diesel

Colour WHITE

VIN VF1FL000969146630

Body Style Panel Van

MOT Due Expired

CAP Clean £13,450.00

CAP Average £12,250.00

CAP Below £10,300.00

Gearbox MANUAL

Gears 6

Rear Doors Barn

WARNING LIGHT ON DASH AD-BLUE, SINGLE SIDE LOAD DOOR (INOPERABLE),

Tyres

NSF

NSR

OSF

OSR Punctured

Spare

Features

- Bluetooth connection
- Rear parking sensor
- Front electric windows
- Central locking
- Cruise control
- Digital radio
- Rear electric windows
- Cloth seat trim
- Navigation system
- USB/iPod interface
- Drivers airbag
- Park assist camera
- Air conditioning
- Passenger airbag


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm

4: Wheel nsf
Scratched
Over 50mm



5: Qtr Panel nsr
Scratched
Over 25mm Thru Paint

6: Handle Outer nsr
Missing
Replace



7: Door Moulding nsf
Scuffed (Unpainted)
UpTo 100mm

8: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



9: Qtr Panel Moulding ns
Scratched (Painted)
Over 25mm Thru Paint

10: Moulding nsf Wing
Broken
Replace



11: Qtr Panel nsr
Scratched
Over 25mm Thru Paint

12: Qtr Panel Moulding ns
Missing
Replace



13: Sill ns
Dented
Over 30mm

14: Wheel nsr
Scratched
Up To 50mm



15: Qtr Panel Moulding ns
Scratched (Painted)
Over 25mm Thru Paint

16: Door osr
Chipped
Over 5mm



17: Door osr
Scratched
Over 25mm Thru Paint

18: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm



19: Other
N/A
N/A

20: Qtr Panel osr
Dented
Over 30mm



21: Qtr Panel osr
Scratched
Over 25mm Thru Paint



22: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm




23: Door Mirror Assy osf
Scratched (Painted)
UpTo 25mm Thru Paint




24: Bumper Front
Chipped
Multiple Chips



25: Bumper Front
Scratched
Over 100mm Thru Paint



26: Seat Base Cover osf
Soiled
Heavy





27: Seat Base Cover nsr
Soiled
Heavy

28: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition		OK	Upholstery Condition		OK
Seat Condition		Poor	Odour		Yes
Engine Runs	OK		No Excessive Smoking	OK	
EML light illuminated	OK		Oil warning light illuminated	OK	
Airbag light illuminated	OK		DPF light illuminated	Fault	
ABS light illuminated	OK		Service indicator light illuminated	OK	