

VEHICLE INSPECTION REPORT

HX69VYD

Mercedes-Benz Sprinter 314 CDI

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT
V5 Buyer To Apply

Details

Reg. date	30/09/2019	VIN	WDB9106332P150133	CAP Below	£7,025.00
Year	2019	Body Style	Panel Van MWB	Gearbox	MANUAL
Mileage	86,342 Miles Warranted	MOT Due	08/10/2025	Axle Combi	4x2
Fuel Type	Diesel	CAP Clean	£10,000.00		
Colour	WHITE	CAP Average	£8,750.00		

A/C, AD-BLUE, SINGLE SIDE DOOR, REAR SENSORS, E/WINDOWS

WARNING LIGHT ON DASH, NO ORIGINAL V5, COPY OF V5 AVAILABLE AT REQUEST

Tyres

NSF

NSR

OSF

OSR


Spare

Photos





Condition Check



Damage Photos



1: Screen Front
Chipped
Over 10mm



2: Bonnet
Chipped
Multiple Chips



3: Bumper Front
Scratched
Over 25mm Not Thru Paint



4: Bumper Front
Scratched
Over 25mm Not Thru Paint



5: Door nsf
Scratched
Over 25mm Thru Paint



6: Door nsr
Scratched
Over 25mm Thru Paint



7: Door nsr
Scratched
Over 25mm Thru Paint



8: Qtr Panel nsr
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK