

VEHICLE INSPECTION REPORT

SJ65GKG

MERCEDES-BENZ ANTOS 1827

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT
V5 To Follow

Details

Reg. date	13/11/2015	VIN	WDB9630032L994226	Axle Combi	4x2
Year	2015	Body Style	Fridge Box	Rear Suspension	Steel
Mileage	400,363 Km Warranted	MOT Due	31/05/2026	Rear Doors	Barn
Fuel Type	Diesel	Cab Type	DAY CAB	Tail Lift	Tuckaway
Colour	WHITE	Gearbox	AUTOMATIC		




FRIGOBLOCK FK24 UNIT


Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4


Photos








Condition Check



Damage Photos



1: Wing osf
Scratched
Over 25mm Not Thru Paint

2: Other
N/A
N/A



3: Bonnet
Chipped
1 To 5

4: Other
N/A
N/A



5: Wing nsf
Scratched
Over 25mm Not Thru Paint

6: Door nsf
Scratched
Over 25mm Not Thru Paint



7: Other
N/A
N/A

8: Other
N/A
N/A



9: Other
N/A
N/A

10: Other
N/A
N/A



11: Other
N/A
N/A

12: Other
N/A
N/A



13: Other
N/A
N/A

14: Door osf
Scratched
Over 25mm Thru Paint



15: Seat Base Cover osf
 Holed
 Over 3mm

16: Other
 N/A
 N/A



17: Door osf
 Chipped
 Edge Chip

Interior

Carpet Condition	Average		Upholstery Condition	Average
Seat Condition	Average		Odour	-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK
Brakes	OK		Clutch Slip Test from Static	OK
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK
			No Excessive Smoking	OK
EML light illuminated	OK		Oil warning light illuminated	OK
Airbag light illuminated	OK		DPF light illuminated	OK
ABS light illuminated	OK		Service indicator light illuminated	OK