

VEHICLE INSPECTION REPORT

SJ65GKC

Mercedes-Benz Antos 1827

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 04/11/2015

VIN WDB9630032L992998

Axle Combi 4x2

Year 2015

Body Style Fridge Box

Rear Suspension Steel

Mileage 417,680 Km Warranted

MOT Due 30/04/2026

Rear Doors Barn

Fuel Type Diesel

Cab Type SLEEPER CAB

Tail Lift Tuckaway

Colour WHITE

Gearbox AUTOMATIC

FRIGOBLOCK FK24 UNIT

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1



OSO2


OSO3

OSO4


Photos







Condition Check



Damage Photos



1: Wing osf
Scratched
Over 25mm Not Thru Paint

2: Other
N/A
N/A



3: Other
N/A
N/A

4: Bonnet
Chipped
Multiple Chips



5: Other
N/A
N/A

6: Other
N/A
N/A



7: Other
N/A
N/A

8: Other
N/A
N/A



9: Other
N/A
N/A

10: Other
N/A
N/A



11: Other
N/A
N/A

12: Other
N/A
N/A



13: Other
N/A
N/A

14: Other
N/A
N/A



15: Door osf
Scratched
Over 25mm Thru Paint

16: Door osf
Chipped
Edge Chip



17: Seat Base Cover osf
Holed
Over 3mm

Interior

Carpet Condition		Average		Upholstery Condition		Average	
Seat Condition		Average		Odour		-	
Engine Runs	OK			Gearbox 1st and Reverse Test	OK		
Brakes	OK			Clutch Slip Test from Static	OK		
Turbo Boosting	OK			Gearbox Static Gear Selection (engine running)	OK		
Parking Brake	OK			No Excessive Smoking	OK		
EML light illuminated	OK			Oil warning light illuminated	OK		
Airbag light illuminated	OK			DPF light illuminated	OK		
ABS light illuminated	OK			Service indicator light illuminated	OK		