

VEHICLE INSPECTION REPORT

PK67VFW

Daf CF 450

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 09/11/2017

VIN XLRTGM4100G181530

Gearbox AUTOMATIC

Year 2017

Body Style Tractor Unit

Axle Combi 6x2

Mileage 927,990 Km Warranted

Service history Yes

Steering Combi Mid-Lift

Fuel Type Diesel

MOT Due 31/10/2026

Rear Suspension Air

Colour RED

Cab Type SLEEPER CAB

Tyres

NSF NSI1 NSI2 NSI3 NSI4

OSF OSI1 OSI2 OSI3 OSI4

Spare NSO1 NSO2 NSO3 NSO4






OSO1 OSO2 OSO3 OSO4


Features

- Air conditioning


Photos







Condition Check



Damage Photos



1: Wing of
Cracked
Replace



2: Bumper Front
Scratched
Over 25mm Not Thru Paint



3: Bonnet
Chipped
Multiple Chips



4: Bumper Front
Scratched
25 to 100mm Thru Paint



5: Wing nsf
Chipped
Multiple Chips



6: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



7: Wing Front Arch Extension ns
Scratched (Painted)
Over 25mm Not Thru Paint

8: Door nsf
Scratched
Over 25mm Thru Paint



9: Door osf
Dented
With Paint Damage

10: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm



11: Wing Front Arch Extension os
Scratched (Painted)
Over 25mm Not Thru Paint

12: Door Mirror Assy osf
Broken
Replace



13: Door osf
Scratched
Over 25mm Not Thru Paint

14: Switches And Controls
Broken
Replace

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK