

VEHICLE INSPECTION REPORT

BK14AOP

Iveco Eurocargo 75E16

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 19/03/2014

VIN ZCFA675B302623261

Gearbox MANUAL

Year 2014

Body Style Box Van

Axle Combi 4x2

Mileage 613,195 Km Warranted

Service history Yes

Rear Suspension Steel

Fuel Type Diesel

MOT Due 30/11/2026

Tail Lift Cantilever

Colour RED

Cab Type DAY CAB

COLLECTED AS NON-RUNNER, TURBO ISSUES

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4


OSO1


OSO2

OSO3


OSO4

Photos





Condition Check



Damage Photos



1: Wing osf
Chipped
Multiple Chips

2: Wing nsf
Scratched
Over 25mm Not Thru Paint



3: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm

4: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



5: Bumper Front
Cracked
Over 25mm

6: Door nsf
Scratched
Over 25mm Thru Paint



7: Door nsf
Scratched
Over 25mm Thru Paint

8: Wing Front Arch Extension ns
Scuffed (Unpainted)
Over 100mm



9: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint

10: Bumper Rear
Rusted
Over 5mm



11: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint

12: Door osf
Chipped
Edge Chip



13: Door osf
Scratched
UpTo 25mm Thru Paint

14: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm



15: Switches And Controls
Broken
Replace

16: Switches And Controls
Missing
Replace



17: Fascia Trim
Damaged
Replace

Interior

Carpet Condition	Average		Upholstery Condition	Average
Seat Condition	Average		Odour	-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK
Brakes	OK		Clutch Slip Test from Static	OK
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK
			No Excessive Smoking	OK
EML light illuminated	OK		Oil warning light illuminated	OK
Airbag light illuminated	OK		DPF light illuminated	OK
ABS light illuminated	OK		Service indicator light illuminated	OK