

VEHICLE INSPECTION REPORT

SH71GHZ

Fiat Doblo Work Up 1.6 MULTIJET 16V II

Non Runner

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 31/12/2021

Colour WHITE

Gearbox MANUAL

Year 2021

VIN ZFA26300006V66853

Gears 5

Mileage 52,821 Miles
Warranted

Body Style MILK FLOAT

MOT Due Expired

Fuel Type Diesel

NON-RUNNER, ENGINE PARTS REMOVED AD-BLUE

Tyres

NSF

NSR

OSF

OSR


Spare

Features

- Radio/CD
- Front electric windows
- Drivers airbag
- Central locking
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bumper Front
Cracked
Over 25mm

2: Bumper Front Moulding
Broken
Replace



3: Bumper Front Moulding
Missing
Replace

4: Bonnet
Dented
With Paint Damage



5: Bumper Front
Insecure
Action Required

6: Door Moulding nsf
Missing
Replace



7: Door Mirror Assy nsf
Broken
Replace

8: Door nsf
Dented
With Paint Damage



9: Qtr Panel nsr
Dented
Over 30mm

10: Lamp nsr
Broken
Replace



11: Panel Rear
Cracked
Replace

12: Door osf
Dented
Over 30mm



13: Fascia Panel
Missing
Replace

14: Seat Base Cover osf
Holed
Over 3mm



15: Fascia Panel
Missing
Replace

16: Seat Base Cover nsf
Soiled
Heavy



17: Wheel osf
Dented
Over 30mm (Steel)

18: Wheel osr
Dented
Over 30mm (Steel)

Interior

Carpet Condition	OK
Seat Condition	Poor
Engine Runs	Fault

Upholstery Condition	Poor
Odour	No