

VEHICLE INSPECTION REPORT

SA71KKE

Fiat Doblo Work Up 1.6 MULTIJET 16V II

Non Runner

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT
V5 To Follow

Details

Reg. date	08/11/2021	Colour	WHITE	Gearbox	MANUAL
Year	2021	VIN	ZFA26300006V28086	Gears	5
Mileage	80,293 Miles Warranted	Body Style	MILK FLOAT		
Fuel Type	Diesel	MOT Due	Expired		

NON-RUNNER, SUSPECTED ENGINE FAILURE, PARTS REMOVED AD-BLUE

Tyres

NSF

NSR

OSF

OSR

Spare

Features

- Radio/CD
- Central locking
- Front electric windows
- Cloth seat trim
- Drivers airbag
- Passenger airbag


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Bumper Front
Poor Previous Repair
Poor Colour



3: Wing nsf
Dented
Over 30mm

4: Door Mirror Assy nsf
Broken
Replace



5: Qtr Panel nsr
Dented
Over 30mm

6: Qtr Panel nsr
Dented
Over 30mm



7: Wheel nsr
Damaged
Replace

8: Panel Rear
Cracked
Replace



9: Wheel osr
Damaged
Replace



10: Door Mirror Assy osf
Broken
Replace




11: Carpets Front
Holed
Over 3mm



12: Seat Base Cover osf
Soiled
Heavy



13: Seat Base Cover nsf
Soiled
Heavy



14: Seat Back Cover nsf
Soiled
Heavy



15: Fascia Panel
Missing
Replace

16: Fascia Panel
Missing
Replace

Interior

Carpet Condition Poor
Seat Condition Poor

Upholstery Condition Poor
Odour No

Engine Runs **Fault**