

VEHICLE INSPECTION REPORT

SJ71HTK

Fiat Doblo Work Up 1.6 MULTIJET 16V II

Non Runner

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 18/10/2021

Colour WHITE

Gearbox MANUAL

Year 2021

VIN ZFA26300006V14500

Gears 5

Mileage 62,685 Miles
Warranted

Body Style MILK FLOAT

MOT Due 17/10/2026

Fuel Type Diesel

NON-RUNNER, SUSPECTED ENGINE FAILURE AD-BLUE

Tyres

NSF

NSR

OSF

OSR


Spare

Features

- Park assist camera
- Rear parking sensor
- Front electric windows
- Central locking


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Bumper Front Moulding
Missing
Replace



3: Number Plate Front
Broken
Replace

4: Bumper Front
Scratched
25 to 100mm Thru Paint



5: Door nsf
Scratched
Over 25mm Thru Paint

6: Door nsf
Scratched
Over 25mm Thru Paint



7: Door nsf
Dented
Over 30mm

8: Qtr Panel nsr
Dented
Over 30mm



9: Lamp nsr
Broken
Replace

10: Panel Rear
Cracked
Replace



11: Door Moulding osf
Missing
Replace

12: Door osf
Dented
With Paint Damage




13: Door osf
Dented
With Paint Damage

14: Carpets Front
Holed
Over 3mm



15: Fascia Panel
Broken
Replace

16: Seat Base Cover osf
Holed
Over 3mm



17: Seat Back Cover osf
Holed
Over 3mm

18: Seat Base Cover nsf
Soiled
Heavy

Interior

Carpet Condition	Poor	Upholstery Condition	Poor
Seat Condition	Poor	Odour	No
Engine Runs		Fault	