

VEHICLE INSPECTION REPORT

SA71KKH

Fiat Doblo Work Up 1.6 MULTIJET 16V II

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 08/11/2021

Year 2021

Mileage 74,063 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN ZFA26300006V20393

Body Style MILK FLOAT

MOT Due Expired

Gearbox MANUAL

Gears 5

ENGINE FAILURE- SUSPECTED TIMING BELT AD-BLUE

Tyres

NSF Punctured

NSR

OSF

OSR




Spare

Features

- Radio/CD
- Central locking
- Front electric windows
- Cloth seat trim
- Drivers airbag
- Passenger airbag


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Other
N/A
N/A

4: Door nsf
Scratched
Over 25mm Thru Paint



5: Qtr Panel nsr
Dented
With Paint Damage

6: Panel Rear
Cracked
Replace



7: Lamp nsr
Broken
Replace

8: Bumper Rear
Dented
Over 30mm



9: Qtr Panel osr
Dented
With Paint Damage

10: Qtr Panel osr
Scratched
Over 25mm Thru Paint




11: Door osf
Dented
With Paint Damage

12: Wing osf
Dented
With Paint Damage



13: Fascia Panel
Missing
Replace

14: Carpets Front
Holed
Over 3mm



15: Seat Base Cover osf
Holed
Over 3mm

16: Seat Back Cover osf
Holed
Over 3mm



17: Seat Base Cover nsf
Soiled
Heavy

Interior

Carpet Condition	Poor	Upholstery Condition	Poor
Seat Condition	Poor	Odour	No
Engine Runs	OK	No Excessive Smoking	Fault
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		