

VEHICLE INSPECTION REPORT

SA71KJK

Fiat Doblo Work Up 1.6 MULTIJET 16V II

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 22/11/2021

Year 2021

Mileage 74,978 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN ZFA26300006V20451

Body Style MILK FLOAT

MOT Due Expired

Gearbox MANUAL

Gears 5

SMOKING, WARNING LIGHT ON DASH AD-BLUE

Tyres

NSF

NSR

OSF


OSR



Spare

Features

- Park assist camera
- Radio/CD
- Front electric windows
- Drivers airbag
- Passenger airbag
- Central locking
- Cloth seat trim


Photos








Condition Check



Damage Photos



1: Bonnet
Dented
With Paint Damage

2: Headlamps
Broken
Replace



3: Bumper Front
Cracked
Over 25mm

4: Wing nsf
Dented
With Paint Damage



5: Qtr Panel nsr
Dented
Over 30mm

6: Panel Rear
Cracked
Replace




7: Door osf
Dented
With Paint Damage

8: Wing osf
Dented
With Paint Damage



9: Door Mirror Assy osf
Broken
Replace

10: Fascia Panel
Missing
Replace




11: Fascia Panel
Missing
Replace

12: Seat Base Cover osf
Holed
Over 3mm



13: Seat Back Cover osf
Soiled
Heavy

14: Carpets Front
Holed
Over 3mm



15: Dash Warning Lights
 Displayed
 No Action

16: Seat Base Cover nsf
 Soiled
 Heavy

Interior

Carpet Condition	Poor		Upholstery Condition	Poor
Seat Condition	Poor		Odour	No
Engine Runs	OK		No Excessive Smoking	Fault
EML light illuminated	Fault		DPF light illuminated	OK
ABS light illuminated	OK			