

VEHICLE INSPECTION REPORT

YD67FEF

Daf LF 230

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date	04/12/2017	Colour	BLUE	Cab Type	DAY CAB
Year	2017	VIN	XLRAEL3700L468794	Gearbox	MANUAL
Mileage	199,751 Km Warranted	Body Style	Dropside & Crane	Axle Combi	4x2
Fuel Type	Diesel	MOT Due	31/07/2026	Rear Suspension	Steel

SERVICE SCHEDULE LIST AVAILABLE, HMF 1420K REMOTE CRANE (YEAR 2017), SURROUND CAMERA SYSTEM

Tyres



NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Park assist camera

Photos





Condition Check



Damage Photos



1: Wing osf
Scratched
Over 25mm Thru Paint

2: Other
N/A
N/A



3: Bumper Front Moulding
Scratched (Painted)
Over 25mm Not Thru Paint

4: Bonnet
Scratched
Over 25mm Not Thru Paint



5: Bumper Front
Cracked
Over 25mm

6: Bumper Front Moulding
Scratched (Painted)
Over 25mm Thru Paint



7: Other
N/A
N/A

8: Other
N/A
N/A



9: Door nsf
Scratched
Over 25mm Not Thru Paint

10: Other
N/A
N/A



11: Other
N/A
N/A

12: Bumper Rear
Rusted
Over 5mm



13: Other
N/A
N/A

14: Door osf
Scratched
Over 25mm Not Thru Paint



15: Door Moulding osf
Missing
Replace

16: Seat Base Cover osf
Holed
Over 3mm

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK	
Brakes	OK		Clutch Slip Test from Static	OK	
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK	
			No Excessive Smoking	OK	
EML light illuminated	OK		Oil warning light illuminated	OK	
Airbag light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	OK		Service indicator light illuminated	OK	