

# VEHICLE INSPECTION REPORT

**KU68EUY**

## Mercedes-Benz Sprinter 314 CDI

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 Present

### Details

Reg. date 06/11/2018

VIN WDB9071352N005009

CAP Below £12,800.00

Year 2018

Body Style Luton LWB

Gearbox MANUAL

Mileage 125,409 Miles Not Warranted

MOT Due 25/09/2025

Axle Combi 4x2

CAP Clean £8,600.00

Tail Lift Column

Fuel Type Diesel

CAP Average £11,000.00

Colour WHITE

AD-BLUE, COLUMN TAIL LIFT, E/WINDOWS

### Tyres

NSF

NSR


OSF

OSR


Spare

### Photos





## Condition Check



## Damage Photos



1: Bumper Front  
Dented  
Between 10mm + 30mm



2: Bumper Front Moulding  
Broken  
Replace



3: Screen Front  
Chipped  
UpTo 10mm



4: Door Mirror Glass ns  
Broken  
Replace




5: Door Mirror Glass ns  
Missing  
Replace



6: C Post ns  
Hole  
Over 10mm



7: General Exterior  
Soiled  
Light



8: General Exterior  
Soiled  
Light



9: General Exterior  
Soiled  
Light



10: General Exterior  
Soiled  
Light



11: Door Mirror Assy osf  
Broken  
Replace



12: Seat Base Cover nsf  
Holed  
Over 3mm

**Interior**

**Carpet Condition**      Average  
**Seat Condition**      Average

**Upholstery Condition**      Average  
**Odour**      No

Airbag light illuminated      Fault