

VEHICLE INSPECTION REPORT

DE24KOA

Volkswagen Crafter CR35 2.0 TDI 140PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 09/05/2024

Year 2024

Mileage 32,296 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN WV1ZZZSYXR9056918

Body Style Panel Van LWB

MOT Due 08/05/2027

CAP Clean £26,550.00

CAP Average £25,000.00

CAP Below £22,000.00

Gearbox AUTOMATIC

Gears 8

WARNING LIGHT ON DASH AD-BLUE, SIDE LOADING DOOR, E/MIRRORS

Tyres

NSF

NSR

OSF


OSR

Spare

Features


- Front parking sensor
- Park assist camera
- Rear parking sensor
- Air conditioning
- Front electric windows

Photos





Condition Check



Damage Photos



1: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm

2: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm




3: Door Moulding nsf
Scuffed (Unpainted)
UpTo 100mm

4: Door nsr
Dented
Over 30mm



5: Door nsr
Dented
Over 30mm

6: Door nsr
Dented
With Paint Damage



7: Door Moulding nsr
Scratched (Painted)
Over 25mm Not Thru Paint

8: Sill ns
Dented
With Paint Damage



9: Other
N/A
N/A

10: Qtr Panel osr
Dented
Over 30% Of Panel



11: Qtr Panel Moulding os
Broken
Replace

12: Qtr Panel Moulding os
Broken
Replace



13: Seat Base Cover osf
Burn
Over 3mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK