

VEHICLE INSPECTION REPORT

DA23BVR

Volkswagen Crafter CR35 2.0 TDI 140PS

Inspection

Serious Damage? No

Vehicle

VAT VAT Qualifying

V5 Present

Details

Reg. date 31/05/2023

Year 2023

Mileage 78,282 Miles Not Warranted

Fuel Type Diesel

Colour WHITE

VIN WV1ZZZSY2P9055923

Body Style Panel Van MWB

MOT Due 30/05/2026

CAP Clean £15,500.00

CAP Average £14,350.00

CAP Below £12,300.00

Gearbox MANUAL

Gears 6

WARNING LIGHT ON DASH INTERIOR PARTS STRIPPED, SIDE LOAD DOOR, AD-BLUE.

Tyres

NSF

NSR

OSF


OSR



Spare

Features


- Radio/CD
- Air conditioning
- Front electric windows
- Central locking

Photos





Condition Check



Damage Photos



1: Carpets Front
Missing
Replace

2: Door Pad osf
Missing
Replace



3: Sill os
Scratched
Over 25mm Thru Paint

4: Roof
Dented
With Paint Damage



5: Bonnet
Dented
With Paint Damage

6: Headlamp ns
Missing
Replace



7: Bumper Front Moulding
Broken
Replace

8: Door osf
Dented
With Paint Damage



9: Qtr Panel osr
Dented
With Paint Damage

10: Sill os
Dented
With Paint Damage



11: Tailgate
Dented
With Paint Damage

12: Fog Lamp osr
Broken
Replace



13: Bumper Rear Moulding
Broken
Replace

14: Badgedecal Rear
Broken
Replace



15: Fog Lamp nsr
Broken
Replace

16: Qtr Panel nsr
Dented
With Paint Damage



17: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm

18: Sill ns
Dented
With Paint Damage



19: Door nsr
Dented
With Paint Damage

20: Door nsf
Dented
With Paint Damage



21: Door Mirror Glass ns
Broken
Replace

22: Door Mirror Assy nsf
Broken
Replace



23: Wing nsf
Dented
Over 30mm

24: Screen Front
Cracked
Replace



25: Handle Outer osf
Missing
Replace

Interior

Carpet Condition	Poor	Upholstery Condition	Poor
Seat Condition	Average	Odour	No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	Fault	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	Fault	Radio	OK
		Steering	OK