

VEHICLE INSPECTION REPORT

PJ73KUW

Volkswagen Crafter CR35 2.0 TDI 140PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 13/12/2023

Year 2023

Mileage 67,806 Miles Not Warranted

Fuel Type Diesel

Colour WHITE

VIN WV1ZZZSY8R9024081

Body Style Panel Van MWB

MOT Due 12/12/2026

CAP Clean £16,800.00

CAP Average £15,550.00

CAP Below £13,400.00

Gearbox MANUAL

Gears 6

WARNING LIGHT ON DASH SIDE LOAD DOOR, AD-BLUE.

Tyres

NSF

NSR

OSF


OSR

Spare

Features


- Rear parking sensor
- Radio/CD
- Air conditioning
- Front electric windows

Photos





Condition Check



Damage Photos



1: Seat Base Cover nsr
Torn
Over 3mm



2: Sill os
Scratched
Over 25mm Thru Paint



3: Bonnet
Dented
Over 30mm

4: Door osf
Dented
Over 30mm



5: Qtr Panel Moulding os
Broken
Replace

6: Qtr Panel osr
Dented
With Paint Damage



7: Bumper Rear Moulding
Broken
Replace

8: Sill ns
Dented
With Paint Damage



9: Door nsr
Dented
Over 30mm

10: Door nsf
Dented
Over 2 UpTo 10mm

Interior

Carpet Condition		Upholstery Condition	
Seat Condition	Average	Odour	Average
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK