

VEHICLE INSPECTION REPORT

PJ73LSX

Volkswagen Crafter CR35 2.0 TDI 140PS

Inspection

Serious Damage? No

Vehicle

VAT VAT Qualifying

V5 Present

Details

Reg. date 13/12/2023

Year 2023

Mileage 57,829 Miles Not Warranted

Fuel Type Diesel

Colour BLUE

VIN WV1ZZZSY4R9024109

Body Style Panel Van MWB

MOT Due 12/12/2026

CAP Clean £17,700.00

CAP Average £16,400.00

CAP Below £14,100.00

Gearbox MANUAL

Gears 6

WARNING LIGHT ON DASH SIDE LOAD DOOR, TOW BAR, AD-BLUE.

Tyres

NSF

NSR

OSF


OSR

Spare

Features


- Rear parking sensor
- Radio/CD
- Air conditioning
- Front electric windows
- Central locking

Photos





Condition Check



Damage Photos



1: Carpets Front
Missing
Replace

2: Bonnet
Dented
With Paint Damage



3: Door osf
Dented
With Paint Damage



4: Sill os
Dented
With Paint Damage



5: Qtr Panel osr
Dented
With Paint Damage



6: Fog Lamp osr
Broken
Replace



7: Tailgate
Dented
Over 30mm



8: Badgedecal Rear
Missing
Replace



9: Bumper Rear Moulding
Scuffed (Unpainted)
Over 100mm

10: D Post ns
Dented
With Paint Damage



11: Qtr Panel nsr
Dented
With Paint Damage

12: Door nsr
Dented
With Paint Damage



13: Door nsf
Dented
With Paint Damage

Interior

Carpet Condition		Upholstery Condition	
Seat Condition	Average Poor	Odour	Average No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	Fault	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	Fault		
Windows	OK	Radio	OK
		Steering	OK