

VEHICLE INSPECTION REPORT

DU23FRJ

Volkswagen Crafter CR35 2.0 TDI 140PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 31/05/2023

Year 2023

Mileage 60,498 Miles Not Warranted

Fuel Type Diesel

Colour WHITE

VIN WV1ZZZSY8P9046966

Body Style Panel Van MWB

MOT Due 30/05/2026

CAP Clean £18,950.00

CAP Average £17,500.00

CAP Below £15,100.00

Gearbox MANUAL

Gears 6

SIDE LOAD DOOR, AD-BLUE.

Tyres

NSF

NSR

OSF


OSR


Spare

Features


- Rear parking sensor
- Radio/CD
- Air conditioning
- Front electric windows
- Central locking

Photos





Condition Check



Damage Photos



1: Seat Base Cover of
Torn
Over 3mm



2: Carpets Front
Torn
Over 10mm



3: Sill os
Scratched
Over 25mm Thru Paint

4: Bonnet
Dented
Over 30mm



5: Door osf
Dented
Over 2 UpTo 10mm

6: Qtr Panel osr
Dented
Over 30mm



7: Sill os
Dented
With Paint Damage

8: Bumper Rear Moulding
Broken
Replace



9: Fog Lamp osr
Broken
Replace

10: Tailgate
Dented
With Paint Damage



11: Badgedecal Rear
Broken
Replace

12: D Post ns
Dented
With Paint Damage



13: Qtr Panel nsr
Dented
Over 30mm

14: Qtr Panel nsr
Dented
With Paint Damage



15: Door nsr
Dented
With Paint Damage

16: Roof
Dented
With Paint Damage



17: Sill ns
Dented
With Paint Damage

18: Door Mirror Glass ns
Broken
Replace



19: Flasher Side Repeater ns
Broken
Replace

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Poor	Odour		No
Engine Runs		OK	Gearbox 1st and Reverse Test		OK
Brakes		OK	Clutch Slip Test from Static		OK
Turbo Boosting		OK	Gearbox Static Gear Selection (engine running)		OK
Parking Brake		OK	No Excessive Smoking		OK
EML light illuminated		OK	Oil warning light illuminated		OK
Airbag light illuminated		OK	DPF light illuminated		OK
ABS light illuminated		OK	Service indicator light illuminated		OK
Windows		OK	Radio		OK
			Steering		OK