

VEHICLE INSPECTION REPORT

WX21VCE

Mercedes-Benz VITO TOURIER 119 CDI

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Location	Bedford	Colour	GREY	CAP Average	£16,250.00
Reg. date	22/03/2021	VIN	W1V44770523721898	CAP Below	£13,000.00
Year	2021	Body Style	Minibus	Gearbox	AUTOMATIC
Mileage	113,429 Miles Not Warranted	MOT Due	Expired	Gears	9
Fuel Type	Diesel	CAP Clean	£18,500.00		

AD BLUE, TWIN SIDE LOADING DOORS, E/MIRRORS

Tyres

NSF

NSR

OSF

OSR






Spare

Features

- Front parking sensor
- Park assist camera
- Rear parking sensor
- Air conditioning


Photos







Condition Check



Damage Photos



1: Wing of
Dented
With Paint Damage

2: Bonnet
Poor Previous Repair
Poor Paint



3: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm

4: Door nsr
Scratched
Over 25mm Thru Paint



5: Qtr Panel nsr
Scratched
Over 25mm Thru Paint

6: Bumper Rear
Scratched
25 to 100mm Thru Paint



7: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint

8: Door osr
Dented
With Paint Damage



9: Door osf
Dented
With Paint Damage

10: Door Mirror Assy osf
Broken
Replace

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		No
Engine Runs	OK		Gearbox 1st and Reverse Test		OK
Brakes	OK		Clutch Slip Test from Static		OK
Parking Brake	OK		Gearbox Static Gear Selection (engine running)		OK
			No Excessive Smoking		OK
EML light illuminated	OK		Oil warning light illuminated		OK
Airbag light illuminated	OK		DPF light illuminated		OK
ABS light illuminated	OK		Service indicator light illuminated		Fault