

VEHICLE INSPECTION REPORT

DS72NUP

Vauxhall Movano 3500 2.2 TURBO 140PS DYNAMIC

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Location	Bedford	GVW	3500kg	CAP Clean	£9,875.00
Reg. date	30/11/2022	Colour	WHITE	CAP Average	£9,000.00
Year	2022	VIN	VXEYCBPFC12W00696	CAP Below	£7,550.00
Mileage	51,671 Miles Not Warranted	Body Style	Panel Van L3	Gearbox	MANUAL
Fuel Type	Diesel	MOT Due	28/01/2027	Gears	6

AD-BLUE, SIDE LOAD DOOR, E/ MIRRORS

Tyres

NSF

NSR

OSF

OSR





Spare

Features


- Air conditioning
- Front electric windows

Photos





Condition Check



Damage Photos



1: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



2: Screen Front
Chipped
Over 10mm



3: Number Plate Front
Broken
Replace

4: Door Mirror Assy nsf
Broken
Replace



5: Door nsf
Dented
Over 30% Of Panel

6: Qtr Panel Trim ns
Missing
Replace



7: Door nsr
Dented
With Paint Damage

8: Sill ns
Dented
With Paint Damage



9: Door nsr
Scratched
Over 25mm Not Thru Paint



10: Door osr
Dented
With Paint Damage




11: Door osr
Dented
Between 10mm + 30mm



12: Bumper Rear
Hole
Over 25mm



13: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



14: Qtr Panel osr
Scratched
Over 25mm Thru Paint





15: Door osf
Scratched
Over 25mm Not Thru Paint

16: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm



17: Bumper Rear Moulding
Scuffed (Unpainted)
Over 100mm

18: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint

Interior

Carpet Condition OK
Seat Condition OK

Upholstery Condition OK
Odour No

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK