

VEHICLE INSPECTION REPORT

WR22TYW

Mercedes-Benz Vito Tourer 119 CDI

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present
		Cap Id	49774
		Cap Code	MEVI2019S3YDTA2 6 L

Details

Location	Bedford	GVW	2270kg	CAP Clean	£21,900.00
Reg. date	16/06/2022	Colour	BLACK	CAP Average	£19,900.00
Year	2022	VIN	W1V44770524123753	CAP Below	£16,700.00
Mileage	92,744 Miles Not Warranted	Body Style	Minibus	Gearbox	AUTOMATIC
Fuel Type	Diesel	MOT Due	Expired	Gears	9

TWIN SIDE LOADING DOORS, E/MIRRORS, ALLOY WHEELS


Tyres	
NSF	
NSR	
OSF	
OSR	
Spare	

Features


- Front parking sensor
- Front electric windows
- Navigation system
- Rear parking sensor
- Air conditioning

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Not Thru Paint



3: Qtr Panel nsr
Dented
Over 30mm



4: Qtr Panel nsr
Dented
Over 30mm



5: Tailgate
Dented
With Paint Damage



6: Tailgate
Dented
With Paint Damage



7: Door osf
Scratched
UpTo 25mm Thru Paint

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK