

VEHICLE INSPECTION REPORT



Jaguar I-Pace EV400 HSE

Inspection		Vehicle			
Serious Damage?	No	VAT	VAT Qualifying		
		V5	Buyer To Apply		
Details					
Reg. date	26/07/2021	VIN	SADHA2A16M1617782	CAP Below	£13,850.00
Year	2021	Body Style	Hatchback	Gearbox	AUTOMATIC
Mileage	36,271 Miles Not Warranted	MOT Due	25/07/2025	Gears	1
		CAP Clean	£16,550.00	Doors	5
Fuel Type	Electric	CAP Average	£15,200.00	Axle Combi	4x4
Colour	GREY				
Tyres NSF					
NSR					
OSF					
OSR					
Spare					

Features

- Bluetooth connection
- Navigation system
- Self parking system
 Mobile phone App interface
- Fixed panoramic glass roof Heated door mirrors
- · Air conditioning
- · Folding rear seats
- · Height adjustable drivers seat
- Rear headrests
- Metallic Paint
- Collision avoidance braking
- · Isofix child seat anchor points
- Side airbags
- Central locking

Photos

- - Steering wheel mounted controls USB/iPod interface ٠
 - Front fog lights ٠

 - - Remote central locking

- · Front parking sensor
- Rear parking sensor
- Trip computer ٠ Body coloured bumpers
- ٠ Full size spare wheel
- Roof rails
- •
- Front electric windows •
- Rear armrest
- Steering wheel rake adjustment •
- .
- Drivers airbag Passenger airbag •
- - Tyre pressure monitor
- Leather seat trim

- · Heated front seat Reverse parking aid
- Digital radio Electric door mirrors
- Headlight washers Xenon headlights
- Electrically adjustable drivers seat Electrically adjustable passenger seat
 - Front head restraints
 - Rear electric windows
 - Steering wheel reach adjustment •
 - Blind spot information .
 - •

 - ESP Rear airbags
 - Alarm


- Cruise control Park assist camera . •

 - Front armrest
 - Lumbar support
 - 3x3 point rear seat belts .
 - Curtain airbags •
 - Traction control

 - Sports seats •
- ٠
- - •

 - LED headlights • Climate control
 - ٠

 - Lane departure warning
- ABS




































Condition Check



Damage Photos







2: Door nsr Scratched Over 25mm Not Thru Paint





3: Door nsf Scratched UpTo 25mm Not Thru Paint 4: Bumper Front Scratched Over 25mm Not Thru Paint

Interior

Carpet Condition Seat Condition	OK OK	Upholstery ConditionOKOdourNo	
Engine Runs	Oł	Gearbox 1st and Reverse Test	OK
Brakes	Oł	Clutch Slip Test from Static	OK
Turbo Boosting	Oł	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	Oł	No Excessive Smoking	OK
EML light illuminated	Oł	C Oil warning light illuminated	OK
Airbag light illuminated	Faul	DPF light illuminated	OK
ABS light illuminated	Oł	Service indicator light illuminated	OK