

VEHICLE INSPECTION REPORT

KJ69CBO

Mercedes-Benz Vito Tourer 119 CDI L3

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 14/02/2020

Year 2020

Mileage 56,443 Miles Not Warranted

Fuel Type Diesel

GVW 3200kg

Colour GREY

VIN W1V44770523709761

Body Style Minibus

MOT Due Expired

CAP Clean £23,150.00

CAP Average £20,300.00

CAP Below £16,200.00

Gearbox AUTOMATIC

Gears 9

WARNING LIGHT ON DASH TWIN SIDE LOADING DOORS, AD BLUE, E/MIRRORS, 8 SEATS PLUS DRIVER

Tyres

NSF

NSR

OSF


OSR





Spare

Features


- Front parking sensor
- Navigation system
- Park assist camera
- Rear parking sensor
- Air conditioning
- Front electric windows
- Rear electric windows

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Screen Front
Chipped
Over 10mm



3: Door nsr
Scratched
Over 25mm Thru Paint

4: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



5: Bumper Rear
Scratched
25 to 100mm Thru Paint

6: Door nsr
Chipped
1 To 5



7: Qtr Panel osr
Dented
With Paint Damage

8: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK