

VEHICLE INSPECTION REPORT

OK67ASM

Daf LF 230

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date 12/01/2018

Year 2018

Mileage 392,751 Km Not Warranted

Fuel Type Diesel

Colour RED/WHITE

VIN XLRAEL2700L469583

Body Style Car Transporter

MOT Due 31/12/2026

Cab Type DAY CAB

Gearbox AUTOMATIC

Axle Combi 4x2

Rear Suspension Steel

WARNING LIGHT ON DASH, NO TOP DECK WINCH, SURROUND CAMERA SYSTEM, BELLE SALVAGE SPEC BODY

Tyres

NSF NSI1 NSI2 NSI3 NSI4

OSF OSI1 OSI2 OSI3 OSI4



Spare NSO1 NSO2 NSO3 NSO4




OSO1 OSO2 OSO3 OSO4

Features


- Park assist camera
- Air conditioning

Photos





Condition Check



Damage Photos



1: Wing osf
Scratched
Over 25mm Not Thru Paint



2: Bonnet
Chipped
Multiple Chips



3: Screen Front
Chipped
Over 10mm

4: Wing nsf
Scratched
Over 25mm Thru Paint



5: A Post ns
Chipped
1 To 5

6: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



7: Qtr Panel Trim ns
Scuffed
UpTo 25mm

8: Qtr Panel Trim os
Scuffed
UpTo 25mm



9: Door osf
 Chipped
 Edge Chip

Interior

Carpet Condition	Average		Upholstery Condition	Average
Seat Condition	Average		Odour	-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK
Brakes	OK		Clutch Slip Test from Static	OK
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK
			No Excessive Smoking	OK
EML light illuminated	OK		Oil warning light illuminated	OK
Airbag light illuminated	OK		DPF light illuminated	OK
ABS light illuminated	OK		Service indicator light illuminated	OK