

VEHICLE INSPECTION REPORT

DG18SUH

Isuzu N75 190

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 03/04/2018

VIN JAANPR75MH7100603

Axle Combi 4x2

Year 2018

Body Style Beavertail

Rear Suspension Steel

Mileage 307,042 Km Warranted

MOT Due 31/07/2026

Tail Lift Cantilever

Fuel Type Diesel

Cab Type DAY CAB

Colour BLUE/YELLOW

Gearbox AUTOMATIC

WARNING LIGHTS ON DASH NO ELECTRICAL PLUG FOR RAMP, SERVICE SCHEDULE LIST AVAILABLE, WINCH, SURROUND CAMERA SYSTEM

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2

OSO3


OSO4

Features


- Park assist camera

Photos





Condition Check



Damage Photos



1: Bumper Front
Scratched
Over 25mm Not Thru Paint

2: Bumper Front
Scratched
Over 25mm Not Thru Paint



3: Bonnet
Dented
Between 10mm + 30mm

4: Grille Front
Broken
Replace



5: Bonnet
Dented
With Paint Damage

6: Panel Front
Scratched
Over 25mm Thru Paint



7: Door Mirror Assy nsf
Broken
Replace

8: Door nsf
Dented
Between 10mm + 30mm



9: Door nsf
Dented
With Paint Damage

10: Door nsf
Chipped
Edge Chip



11: Bumper Rear
Dented
Over 30mm

12: Door osf
Dented
Between 10mm + 30mm



13: Door osf
Dented
Over 30mm

14: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm



15: Door osf
Chipped
Edge Chip

16: Seat Base Cover osf
Holed
Over 3mm

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		-
Engine Runs		OK	Gearbox 1st and Reverse Test		OK
Brakes		OK	Clutch Slip Test from Static		OK
Parking Brake		OK	Gearbox Static Gear Selection (engine running)		OK
			No Excessive Smoking		OK
EML light illuminated		Fault	Oil warning light illuminated		OK
Airbag light illuminated		OK	DPF light illuminated		OK
ABS light illuminated		Fault	Service indicator light illuminated		OK