

VEHICLE INSPECTION REPORT

GK21RYD

Volkswagen Crafter CR35 2.0 TDI 140PS

Non Runner

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT
V5 Buyer To Apply

Details

Reg. date	15/03/2021	VIN	WV1ZZSYZM9037857	CAP Below	£7,600.00
Year	2021	Body Style	Panel Van LWB	Gearbox	MANUAL
Mileage	130,983 Miles Not Warranted	MOT Due	Expired	Gears	6
Fuel Type	Diesel	CAP Clean	£10,400.00		
Colour	WHITE	CAP Average	£9,250.00		

NON-RUNNER, CRANKS BUT WILL NOT FIRE, KEY STUCK IN BARRELL SIDE LOADING DOOR, E/MIRRORS

Tyres

NSF

NSR

OSF


OSR


Spare

Features


- Air conditioning
- Front electric windows

Photos





Condition Check



Damage Photos



1: Wing of
Dented
With Paint Damage

2: Bonnet
Dented
Over 30% Of Panel



3: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm

4: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



5: Screen Front
Chipped
Over 10mm

6: Wing nsf
Dented
With Paint Damage



7: Headlamp ns
Broken
Replace

8: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



9: Sill ns
Dented
With Paint Damage



10: Door Moulding nsr
Scuffed (Unpainted)
Over 100mm



11: Door nsr
Scratched
Over 25mm Thru Paint



12: Door nsr
Dented
With Paint Damage



13: Qtr Panel nsr
Dented
Between 10mm + 30mm



14: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm



15: Qtr Panel nsr
Dented
With Paint Damage



16: Qtr Panel nsr
Dented
With Paint Damage



17: Qtr Panel nsr
Dented
Over 30mm



18: Bumper Rear
Hole
Over 25mm



19: Door Moulding nsr
Broken
Replace



20: Door nsr
Scratched
Over 25mm Thru Paint



21: Badgedecal Rear
Missing
Replace

22: Door nsr
Dented
With Paint Damage



23: Badgedecal Rear
Missing
Replace

24: Door osr
Hole
Over 10mm



25: Door osr
Dented
With Paint Damage

26: Door Moulding osr
Missing
Replace



27: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint

28: Qtr Panel osr
Dented
With Paint Damage



29: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm

30: Qtr Panel osr
Dented
With Paint Damage



31: Qtr Panel osr
Dented
With Paint Damage

32: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm



33: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint

34: Qtr Panel osr
Dented
Between 10mm + 30mm



35: Door osf
Dented
Between 10mm + 30mm

36: Door osf
Chipped
Edge Chip



37: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm

38: Seat Base Cover osf
Holed
Over 3mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No
Engine Runs		Fault	