

VEHICLE INSPECTION REPORT

GL21YJE

Volkswagen Crafter CR35 2.0 TDI 140PS

Non Runner

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT
V5 Buyer To Apply

Details

Reg. date	01/03/2021	VIN	WV1ZZSYZM9034132	CAP Below	£9,050.00
Year	2021	Body Style	Panel Van LWB	Gearbox	MANUAL
Mileage	105,317 Miles Not Warranted	MOT Due	01/03/2026	Gears	6
Fuel Type	Diesel	CAP Clean	£12,350.00		
Colour	WHITE	CAP Average	£11,000.00		

NON-RUNNER, POWERS UP DOES NOT CRANK, KEY SNAPPED IN BARRELL, NO ACCESS TO SIDE OR REAR DOOR SIDE LOADING DOOR, E/MIRRORS

Tyres

NSF

NSR

OSF



OSR



Spare

Features


- Rear parking sensor
- Air conditioning
- Front electric windows

Photos





Condition Check



Damage Photos



1: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm

2: Wing nsf
Dented
With Paint Damage



3: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm

4: Door nsf
Scratched
Over 25mm Not Thru Paint



5: Door nsr
Scratched
Over 25mm Not Thru Paint

6: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



7: Sill ns
Dented
Over 30mm

8: Door Moulding nsr
Scuffed (Unpainted)
Over 100mm



9: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm

10: Door nsr
Dented
Over 30% Of Panel



11: Door nsr
Dented
Over 30mm

12: Door osr
Dented
Over 30% Of Panel



13: Door osr
Dented
Over 30mm

14: Door osr
Rusted
Holed



15: Qtr Panel osr
Dented
With Paint Damage

16: Qtr Panel osr
Scratched
Over 25mm Thru Paint



17: Sill os
Dented
With Paint Damage

18: Door Window osf
Missing
Replace



19: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm

20: Seat Base Cover osf
Holed
Over 3mm



21: Glove Box Lid
Broken
Replace

22: Fascia Panel
Missing
Replace



23: Switches And Controls
Broken
Replace

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No
Engine Runs	Fault		