

VEHICLE INSPECTION REPORT

BN17EOP

MERCEDES-BENZ ANTOS 1824

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT
V5 To Follow

Details

Reg. date	22/03/2017	VIN	WDB96300320114202	Axle Combi	4x2
Year	2017	Body Style	Curtainside	Rear Suspension	Air
Mileage	238,380 Km Warranted	MOT Due	31/05/2026	Rear Doors	Barn
Fuel Type	Diesel	Cab Type	DAY CAB	Tail Lift	Tuckaway
Colour	WHITE	Gearbox	AUTOMATIC		


Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Park assist camera
- Air conditioning

Photos





Condition Check



Damage Photos



1: Screen Front
Chipped
Over 10mm



2: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



3: Wing Front Arch Extension ns
 Scratched (Painted)
 Over 25mm Thru Paint

4: Door nsr
 Dented
 Over 30mm



5: Bumper Rear
 Rusted
 Over 5mm

6: Door Mirror Assy osf
 Scuffed (Unpainted)
 Over 100mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK