

VEHICLE INSPECTION REPORT

DK69WKC

Isuzu N75 190

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date	14/10/2019	Colour	BLUE/YELLOW	Cab Type	DAY CAB
Year	2019	VIN	JAANPR75MJ7100668	Axle Combi	4x2
Mileage	240,818 Km Warranted	Body Style	Dropside	Rear Suspension	Steel
Fuel Type	Diesel	MOT Due	31/10/2026	Tail Lift	Cantilever

WARNING LIGHT ON DASH REAR VIEW CAMERA.

Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Radio/CD

Photos





Condition Check



Damage Photos



1: Sill os
Rusted
Over 5mm



2: Bonnet
Dented
Over 30mm



3: Door osf
Dented
Over 30mm

4: Qtr Panel osr
Dented
With Paint Damage



5: Tailgate
Rusted
Over 5mm

6: Qtr Panel nsr
Dented
Over 30mm



7: B Post ns
Dented
Over 30mm

8: Door nsf
Dented
Over 30mm

Interior

Carpet Condition	-	Upholstery Condition	-
Seat Condition	-	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK