

VEHICLE INSPECTION REPORT

MK72FMC

Maxus Deliver 9

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 15/02/2023

Year 2023

Mileage 21,343 Miles
Warranted

Fuel Type ELECTRIC

Colour WHITE

VIN LSFAL1109MA121599

Body Style Dropside LWB

MOT Due 14/02/2026

CAP Clean £12,550.00

CAP Average £11,600.00

CAP Below £9,950.00

Gearbox AUTOMATIC

Gears 6

Tail Lift Column

SERVICE SCHEDULE LIST AVAILABLE

Tyres

NSF

NSR

OSF


OSR

Spare

Features


- Front electric windows

Photos





Condition Check



Damage Photos



1: Bumper Front
Scratched
Over 100mm Thru Paint

2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wing Front Arch Extension ns
Scuffed (Unpainted)
Over 100mm

4: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



5: B Post ns
Scratched
Over 25mm Thru Paint

6: Qtr Panel Arch Extension ns
Broken
Replace



7: B Post os
Scratched
Over 25mm Thru Paint

8: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm



9: Door osf
 Scratched
 UpTo 25mm Thru Paint

10: Seat Base Cover osf
 Holed
 Over 3mm

Interior

Carpet Condition		Average		Upholstery Condition		Average	
Seat Condition		Average		Odour		No	
Engine Runs		OK		Gearbox 1st and Reverse Test		OK	
Brakes		OK		Clutch Slip Test from Static		OK	
Parking Brake		OK		Gearbox Static Gear Selection (engine running)		OK	
				No Excessive Smoking		OK	
EML light illuminated		OK		Oil warning light illuminated		OK	
Airbag light illuminated		OK		DPF light illuminated		OK	
ABS light illuminated		OK		Service indicator light illuminated		OK	