

VEHICLE INSPECTION REPORT

YD66EVU

Daf LF 150

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 10/10/2016

VIN XLRAEL1500L453668

Axle Combi 4x2

Year 2016

Body Style Box Van

Rear Suspension Steel

Mileage 390,681 Km Warranted

MOT Due 31/05/2026

Rear Doors Barn

Fuel Type Diesel

Cab Type DAY CAB

Tail Lift Column

Colour SILVER

Gearbox MANUAL

Tyres

NSF NSI1 NSI2 NSI3 NSI4

OSF OSI1 OSI2 OSI3 OSI4


Spare NSO1 NSO2 NSO3 NSO4

OSO1 OSO2 OSO3 OSO4

Features


- Park assist camera

Photos





Condition Check



Damage Photos



1: Wing osf
Scratched
Over 25mm Thru Paint



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Bonnet
Scratched
UpTo 25mm Thru Paint

4: Screen Front
Cracked
Replace



5: Bumper Front
Scratched
25 to 100mm Thru Paint

6: Fog Lamp Surround ns
Broken
Replace



7: Wing nsf
Scratched
Over 25mm Thru Paint

8: Door nsf
Dented
Over 2 UpTo 10mm



9: Badgedecal Front
Broken
Replace

10: Wing Front Arch Extension ns
Scratched (Painted)
Over 25mm Thru Paint



11: Qtr Panel osr
Scratched
Over 25mm Thru Paint

12: Qtr Panel osr
Scratched
Over 25mm Thru Paint



13: Wing Front Arch Extension os
Scratched (Painted)
Over 25mm Thru Paint

14: Seat Base Cover osf
Holed
Over 3mm

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK	
Brakes	OK		Clutch Slip Test from Static	OK	
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK	
			No Excessive Smoking	OK	
EML light illuminated	OK		Oil warning light illuminated	OK	
Airbag light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	OK		Service indicator light illuminated	OK	