



**COMMERCIAL VEHICLE AUCTIONS LTD**  
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate  
Doncaster  
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

# VEHICLE INSPECTION REPORT

**BX13LWO**

## Mitsubishi L200

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT  
V5 Present

### Details

Reg. date	17/05/2013	VIN	MMCCNKB40DD000389	Gearbox	MANUAL
Year	2013	Body Style	Pickup Single Cab	Gears	5
Mileage	132,748 Miles Warranted	CAP Clean	£2,775.00	Axle Combi	4x4
Fuel Type	Diesel	CAP Average	£2,200.00		
Colour	WHITE	CAP Below	£1,450.00		

TOW BAR

Tyres

NSF

NSR

OSF

OSR



Spare

## Features


- Front electric windows

## Photos





## Condition Check



## Damage Photos



1: Wing osf  
Dented  
Over 30mm

2: Wing osf  
Scratched  
Over 25mm Thru Paint



3: Bonnet  
Chipped  
Multiple Chips

4: Screen Front  
Chipped  
Over 10mm



5: Wing nsf  
Dented  
With Paint Damage

6: Door nsf  
Dented  
Over 30mm



7: Sill ns  
Dented  
With Paint Damage

8: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint





9: Qtr Panel nsr  
Chipped  
Multiple Chips

10: Qtr Panel nsr  
Dented  
With Paint Damage



11: Panel Rear  
Rusted  
Over 5mm

12: Qtr Panel osr  
Dented  
Over 30mm



13: Qtr Panel osr  
Scratched  
Over 25mm Thru Paint

14: Qtr Panel osr  
Rusted  
Over 5mm



15: Seat Base Cover osf  
 Holed  
 Over 3mm

**Interior**

<b>Carpet Condition</b>	Average	<b>Upholstery Condition</b>	Average
<b>Seat Condition</b>	Average	<b>Odour</b>	No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK