

VEHICLE INSPECTION REPORT

DK69WJJ

Isuzu N75 190

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 02/10/2019

VIN JAANPR75MJ7100683

Axle Combi 4x2

Year 2019

Body Style Dropside

Rear Suspension Steel

Mileage 235,916 Km Warranted

MOT Due 30/09/2026

Tail Lift Cantilever

Fuel Type Diesel

Cab Type DAY CAB

Colour BLUE/YELLOW

Gearbox AUTOMATIC

WARNING LIGHT ON DASH SERVICE SCHEDULE LIST AVAILABLE, SURROUND CAMERA SYSTEM

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2

OSO3



OSO4

Features

- Park assist camera


Photos







Condition Check



Damage Photos



1: Screen Front
Cracked
Replace



2: Wing osf
Scratched
Over 25mm Not Thru Paint



3: Bumper Front
Scratched
Over 25mm Not Thru Paint

4: Bumper Front
Scratched
Over 25mm Not Thru Paint



5: Bonnet
Dented
With Paint Damage

6: Headlamp os
Broken
Replace



7: Headlamp ns
Broken
Replace

8: Door nsf
Dented
Over 30mm



9: Door Mirror Assy nsf
Broken
Replace

10: Qtr Panel nsr
Dented
With Paint Damage



11: Qtr Panel osr
Dented
With Paint Damage

12: Door osf
Dented
Between 10mm + 30mm




13: Door osf
Dented
Between 10mm + 30mm

14: Door osf
Chipped
Multiple Chips



15: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm

16: Carpets Front
Holed
Over 3mm



17: Seat Base Cover osf
Holed
Over 3mm

18: Centre Console Front
Missing
Replace

Interior

Carpet Condition	Average		Upholstery Condition	Average
Seat Condition	Average		Odour	-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK
Brakes	OK		Clutch Slip Test from Static	OK
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK
			No Excessive Smoking	OK
EML light illuminated	OK		Oil warning light illuminated	OK
Airbag light illuminated	OK		DPF light illuminated	OK
ABS light illuminated	OK		Service indicator light illuminated	Fault