

VEHICLE INSPECTION REPORT

HX15YDH

Daf LF 220

Inspection		Vehicle			
Serious Damage?	No	VAT	Plus VAT		
		V5	Buyer To Apply	- -	
Details					
Reg. date	10/03/2015	Colour	WHITE	Gearbox	MANUAL
Year	2015	VIN	XLRAEL3700L441358	Axle Combi	4x2
Mileage	253,537 Km Not Warranted	Body Style	Skiploader	Rear Suspension	Steel
		Cab Type	DAY CAB		
Fuel Type	Diesel			-	

^{*}POSSIBLE INPUT ERROR ON MOT HISTORY* SHEETING SYSTEM, BOUGHTON BODY (YEAR 2015)

Tyres

NSF	NSI1	NSI2	NSI3	NSI4	
OSF	OSI1	OSI2	OSI3	OSI4	
Spare	NSO1	NSO2	NSO3	NSO4	
	OS01	OSO2	OS03	OSO4	

Features

- Cruise control
 Central locking
- Digital radioCloth seat trim
- Radio/CD

Drivers airbag

Photos































Condition Check



Damage Photos



1: Moulding osf Wing Broken Replace



2: Lamp nsr Broken Replace



3: Door nsf Dented With Paint Damage

Interior

Carpet Condition Seat Condition	Average Average		Upholstery Condition Odour	Average -	
Engine Runs		OK	Gearbox 1st and Revers	se Test	OK
Brakes		OK	Clutch Slip Test from St	atic	OK
Turbo Boosting		OK	Gearbox Static Gear Se	election (engine running)	OK
Parking Brake		OK	No Excessive Smoking		OK
EML light illuminated		OK	Oil warning light illumina	ated	OK
Airbag light illuminated		OK	DPF light illuminated		OK
ABS light illuminated		OK	Service indicator light ille	uminated	OK
Windows		ОК	Radio		OK
			Steering		OK