

VEHICLE INSPECTION REPORT

FJ72VRN

Mercedes-Benz eVito 85KW Progressive

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 10/11/2022

Year 2022

Mileage 47,549 Miles Not Warranted

Fuel Type Electric

Colour WHITE

VIN W1V44760324138658

Body Style Panel Van L2

MOT Due 09/11/2025

CAP Clean £10,000.00

CAP Average £9,250.00

CAP Below £7,950.00

Gearbox AUTOMATIC

WARNING LIGHTS ON DASH TWIN SIDE LOAD DOOR, E/ MIRRORS, HEATED WINDSCREEN, CHARGING CABLES IN REAR

Tyres

NSF

NSR

OSF

OSR


Spare

Features

- Bluetooth connection
- Front electric windows
- Cloth seat trim
- Cruise control
- Drivers airbag
- Park assist camera
- Passenger airbag
- Digital radio
- Central locking


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front Moulding
Missing
Replace



3: Wing nsf
Scratched
Over 25mm Thru Paint



4: Door nsf
Scratched
Over 25mm Thru Paint



5: Door nsf
Dented
Over 30mm



6: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



7: Qtr Panel nsr
Dented
Over 30% Of Panel



8: Qtr Panel nsr
Dented
Over 30mm



9: Qtr Panel osr
Dented
Over 30mm



10: Qtr Panel osr
Scratched
Over 25mm Thru Paint



11: Door Pad osf
Soiled
Heavy



12: Seat Base Cover nsf
Soiled
Heavy

Interior

Carpet Condition	OK	Upholstery Condition	Poor
Seat Condition	Poor	Odour	-
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	Fault	Service indicator light illuminated	OK