

VEHICLE INSPECTION REPORT

FJ72VRP

Mercedes-Benz eVito 66 85KW Progressive

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 10/11/2022

Year 2022

Mileage 38,491 Miles Not Warranted

Fuel Type Electric

Colour WHITE

VIN W1V44760324143019

Body Style Panel Van L2

MOT Due 09/11/2025

CAP Clean £11,150.00

CAP Average £10,300.00

CAP Below £8,875.00

Gearbox AUTOMATIC

WARNING LIGHT ON DASH SIDE LOAD DOOR, E/ MIRRORS, HEATED WINDSCREEN, CHARGING CABLE IN REAR

Tyres

NSF

NSR

OSF

OSR

Spare

Features

- Bluetooth connection
- Cruise control
- Front electric windows
- Drivers airbag
- Passenger airbag
- Central locking
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Door Mirror Assy nsf
Broken
Replace



2:



3: Qtr Panel nsr
Dented
Over 30mm




4: Sill ns
Dented
Over 30mm



5: Qtr Panel nsr
Dented
Over 30mm



6: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



7: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



8: Door nsr
Dented
Over 30mm



9: Bumper Rear Moulding
Scuffed (Unpainted)
Over 100mm



10: Qtr Panel osr
Dented
Over 30mm



11: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



12: Door osf
Dented
Over 30mm



13: Bonnet
Scratched
Over 25mm Not Thru Paint



14: Wing osf
Scratched
Over 25mm Not Thru Paint



15: Door osf
Dented
Between 10mm + 30mm

Interior

| | | | |
|------------------|----|----------------------|----|
| Carpet Condition | OK | Upholstery Condition | OK |
| Seat Condition | OK | Odour | No |
| Engine Runs | OK | | |
| Windows | OK | Radio | OK |