



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

PK67VCM

Daf LF 150

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present

Details


Reg. date	10/11/2017	VIN	XLRAEL1500L471010	Axle Combi	4x2
Year	2017	Body Style	Box Van	Rear Suspension	Steel
Mileage	480,958 Km Warranted	MOT Due	Expired	Tail Lift	Cantilever
Fuel Type	Diesel	Cab Type	DAY CAB		
Colour	RED	Gearbox	MANUAL		





COLLECTED AS NON-RUNNER, RADIATOR/STEERING RACK REQUIRE ATTN

Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Bumper Front
Chipped
Multiple Chips



3: Bumper Front
Dented
With Paint Damage

4: Fog Lamp Surround ns
Broken
Replace



5: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm

6: B Post ns
Dented
With Paint Damage



7: Qtr Panel nsr
Scratched
Over 25mm Thru Paint

8: Bumper Rear
Rusted
Over 5mm



9: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint

10: Door osf
Chipped
Edge Chip



11: Door osf
Scratched
Over 25mm Not Thru Paint

12: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm



13: Door osf
Scratched
Over 25mm Thru Paint

14: Wing osf
Scratched
Over 25mm Thru Paint



15: Seat Base Cover osf
 Holed
 Over 3mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK