

# VEHICLE INSPECTION REPORT

**DY16TXJ**

## Daf LF 220

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 Present

### Details

Reg. date 22/03/2016

Year 2016

Mileage 155,964 Miles  
Warranted

Fuel Type Diesel

Colour WHITE

VIN XLRAEL3700L451548

Body Style Box Van

### Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

## Features

- Cruise control
- Cloth seat trim
- Park assist camera
- Radio/CD
- Front electric windows

## Photos










## Condition Check



## Damage Photos



1: Panel Front  
Scratched  
Over 25mm Thru Paint



2: Bumper Front Moulding  
Broken  
Replace



3: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint



4: Qtr Panel nsr  
Dented  
With Paint Damage



5: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint



6: Qtr Panel nsr  
Cracked  
Replace



7: Lamp nsr  
Broken  
Replace



8: Qtr Panel osr  
Cracked  
Replace



9: Door osf  
 Scratched  
 Over 25mm Thru Paint



10: Door Pad osf  
 Soiled  
 Heavy



11: Door Pad nsf  
 Soiled  
 Heavy

**Interior**

<b>Carpet Condition</b>	OK	<b>Upholstery Condition</b>	Poor
<b>Seat Condition</b>	OK	<b>Odour</b>	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		