



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

WX67JUW

ISUZU D-MAX 1.9 EXTENDED

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Buyer To Apply

Details

Reg. date	01/12/2017	VIN	MPATFS87JHT014145	CAP Below	£3,525.00
Year	2017	Body Style	Pickup Single Cab	Gearbox	MANUAL
Mileage	113,147 Miles Warranted	MOT Due	Expired	Gears	6
Fuel Type	Diesel	CAP Clean	£5,725.00	Axle Combi	4x4
Colour	WHITE	CAP Average	£4,750.00		

COLLECTED AS NON-RUNNER, ALTERNATOR & BATTERY ISSUES TWIN SIDE LOAD DOOR, TOW BAR, E/ MIRRORS, HEATED WINDSCREEN, V5 NEW KEEPER DOCUMENT REFERENCE NUMBER AVAILABLE FOR TAXATION PURPOSES

Tyres


NSF
NSR
OSF
OSR
Spare

Features


- Bluetooth connection
- Drivers airbag
- Park assist camera
- Passenger airbag
- Air conditioning
- Central locking
- Front electric windows
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Dash Warning Lights
Displayed
No Action

2: Bonnet
Scratched
Over 25mm Thru Paint



3: Screen Front
Chipped
Over 10mm

4: Bumper Front
Insecure
Action Required



5: Wing nsf
Dented
With Paint Damage

6: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm




7: Qtr Panel nsr
Cracked
Replace

8: Panel Rear
Scratched
Over 25mm Thru Paint




9: Lamp osf
Broken
Replace

10: Qtr Panel osf
Dented
With Paint Damage



11: Qtr Panel osf
Scratched
Over 25mm Thru Paint

12: Wing osf
Scratched
Over 25mm Thru Paint



13: Door osf
Scratched
Rusted

14: Wing osf
Scratched
Rusted



15: Bumper Front
Cracked
Over 25mm

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
Turbo Boosting	OK		
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		