

VEHICLE INSPECTION REPORT

YF66UTY

Ford Transit 350 2.0 TDCI 130PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 07/11/2016

Year 2016

Mileage 73,298 Miles
Warranted

Fuel Type DIESEL

Colour WHITE

VIN WF0XXXTTGXGY67586

Body Style Panel Van L3

MOT Due Expired

CAP Clean £4,975.00

CAP Average £4,150.00

CAP Below £3,075.00

Gearbox MANUAL

Gears 6

WARNING LIGHT ON DASH SIDE LOADING DOOR

Tyres

NSF

NSR

OSF

OSR

Spare


Features

- Front parking sensor
- Park assist camera
- Rear parking sensor
- Air conditioning
- Front electric windows

Photos



Condition Check



Damage Photos



1: Bonnet
Scratched
Over 25mm Thru Paint



2: Screen Front
Cracked
Replace



3: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm



4: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm



5: Moulding nsf Wing
Missing
Replace



6: Other
N/A
N/A



7: Door nsr
Dented
Between 10mm + 30mm



8: Door Moulding nsr
Missing
Replace



9: Door nsr
Dented
Between 10mm + 30mm



10: Other
N/A
N/A



11: Other
N/A
N/A



12: Qtr Panel nsr
Dented
Between 10mm + 30mm



13: Qtr Panel nsr
Dented
Over 2 UpTo 10mm



14: Qtr Panel nsr
Dented
With Paint Damage



15: Door nsr
Scratched
UpTo 25mm Thru Paint



16: Qtr Panel osr
Dented
With Paint Damage



17: Bumper Rear Moulding
Scuffed (Unpainted)
UpTo 100mm



18: Qtr Panel osr
Dented
With Paint Damage



19: Qtr Panel Arch Extension os
Scuffed (Unpainted)
UpTo 100mm



20: Qtr Panel osr
Dented
Over 2 UpTo 10mm



21: Qtr Panel osr
Dented
With Paint Damage



22: Qtr Panel osr
Dented
Between 10mm + 30mm



23: Qtr Panel Moulding os
Broken
Replace



24: Qtr Panel osr
Dented
Over 30mm



25: Qtr Panel nsr
Dented
Over 2 UpTo 10mm



26: Door Moulding osf
Scuffed (Unpainted)
UpTo 100mm



27: Qtr Panel osr
Dented
Over 30mm



28: Qtr Panel osr
Dented
Between 10mm + 30mm



29: Seat Base Cover osf
Holed
Over 3mm



30: Other
N/A
N/A

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		No
Engine Runs	OK		Gearbox 1st and Reverse Test	OK	
Brakes	OK		Clutch Slip Test from Static	OK	
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK	
			No Excessive Smoking	OK	
EML light illuminated	Fault		Oil warning light illuminated	OK	
Airbag light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	OK		Service indicator light illuminated	OK	