



**COMMERCIAL VEHICLE AUCTIONS LTD**  
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate  
Doncaster  
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

# VEHICLE INSPECTION REPORT

**WN14VGZ**

## Fiat Doblo 1.3 Multijet 16V

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT  
V5 Present

### Details

Reg. date	31/03/2014	VIN	ZFA26300006146406	CAP Below	£600.00
Year	2014	Body Style	Panel Van SWB	Gearbox	MANUAL
Mileage	51,490 Miles Warranted	MOT Due	31/10/2026	Gears	5
Fuel Type	Diesel	CAP Clean	£1,150.00		
Colour	SILVER	CAP Average	£900.00		

\*ONLY RUNS WITH A BOOST PACK, WARNING LIGHT ON DASH\*

### Tyres




NSF
NSR
OSF
OSR
Spare

## Features

- Rear parking sensor
- Drivers airbag
- Radio/CD
- Passenger airbag
- Air conditioning
- Central locking
- Front electric windows
- Cloth seat trim


## Photos







## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips

2: Qtr Panel nsr  
Dented  
With Paint Damage



3: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint

4: Qtr Panel nsr  
Chipped  
Multiple Chips



5: Lamp nsr  
Broken  
Replace

6: Door nsr  
Dented  
With Paint Damage



7: Bumper Rear  
Scratched  
Over 100mm Thru Paint

8: Qtr Panel osr  
Scratched  
Over 25mm Thru Paint



9: Qtr Panel osr  
Dented  
Over 30mm

10: Qtr Panel osr  
Dented  
Over 30mm




11: Wing osf  
Scratched  
Over 25mm Not Thru Paint

12: Carpets Front  
Holed  
Over 3mm



13: Fascia Panel  
Missing  
Replace

14: Seat Base Cover osf  
Holed  
Over 3mm



15: Seat Base Cover nsf  
Soiled  
Heavy

16: Dash Warning Lights  
Displayed  
No Action

**Interior**

**Carpet Condition**            Poor  
**Seat Condition**            Poor

**Upholstery Condition**    Poor  
**Odour**                        No

Engine Runs	Fault		
EML light illuminated	Fault	DPF light illuminated	OK
ABS light illuminated	OK		