



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

KX66YGR

Mercedes-Benz Sprinter 313 CDI

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present

Details					
Reg. date	29/09/2016	Colour	BLUE	Gearbox	MANUAL
Year	2016	VIN	WDB9061352N664786	Gears	6
Mileage	157,832 Miles Warranted	Body Style	Luton LWB	Tail Lift	Column
Fuel Type	Diesel	MOT Due	25/09/2026		


WARNING LIGHTS ON DASH REAR VIEW CAMERA.

Tyres	
NSF	
NSR	
OSF	
OSR	
Spare	

Features


- Radio/CD
- Front electric windows
- Central locking

Photos





Condition Check



Damage Photos



1: Seat Base Cover osf
Torn
Over 3mm



2: Sill os
Rusted
Over 5mm



3: Bonnet
Dented
Over 30mm

4: Door osf
Rusted
Over 5mm



5: Qtr Panel osr
Rusted
UpTo 5mm

6: Tailgate
Rusted
Over 5mm



7: Qtr Panel nsr
Dented
Over 30mm

8: B Post ns
Dented
Over 30mm



9: Door nsf
 Dented
 With Paint Damage

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	Fault	No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	Fault	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK