



COMMERCIAL VEHICLE AUCTIONS LTD  
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate  
Doncaster  
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

# VEHICLE INSPECTION REPORT

**GL21YJC**

## Volkswagen Crafter CR35 2.0 TDI 140PS

| Inspection      |    | Vehicle |                |
|-----------------|----|---------|----------------|
| Serious Damage? | No | VAT     | Plus VAT       |
|                 |    | V5      | Buyer To Apply |

| Details   |                             |             |                   |           |           |
|-----------|-----------------------------|-------------|-------------------|-----------|-----------|
| Reg. date | 01/03/2021                  | VIN         | WV1ZZZSYZM9034206 | CAP Below | £7,300.00 |
| Year      | 2021                        | Body Style  | Panel Van LWB     | Gearbox   | MANUAL    |
| Mileage   | 135,633 Miles Not Warranted | MOT Due     | 09/01/2027        | Gears     | 6         |
| Fuel Type | Diesel                      | CAP Clean   | £10,000.00        |           |           |
| Colour    | WHITE                       | CAP Average | £8,900.00         |           |           |


\*WARNING LIGHT ON DASH, GEARBOX FAULTY\* AD-BLUE, SIDE LOADING DOOR, E/MIRRORS

|       |
|-------|
| Tyres |
| NSF   |
| NSR   |
| OSF   |
| OSR   |
| Spare |

## Features


- Front parking sensor
- Rear parking sensor
- Air conditioning
- Front electric windows

## Photos





## Condition Check



## Damage Photos



1: Wing of  
Dented  
Over 30mm



2: Bonnet  
Chipped  
Multiple Chips



3: Bumper Front Moulding  
Scuffed (Unpainted)  
Over 100mm

4: Bumper Front Moulding  
Scuffed (Unpainted)  
Over 100mm



5: Door Mirror Assy nsf  
Broken  
Replace

6: Wing nsf  
Dented  
Between 10mm + 30mm



7: Door nsf  
Scratched  
Over 25mm Not Thru Paint

8: Door nsr  
Scratched  
Over 25mm Not Thru Paint



9: Qtr Panel nsr  
Dented  
With Paint Damage

10: Qtr Panel nsr  
Dented  
With Paint Damage




11: Sill ns  
Dented  
With Paint Damage

12: Qtr Panel Moulding ns  
Scuffed (Unpainted)  
Over 100mm



13: Qtr Panel nsr  
Scratched  
Over 25mm Not Thru Paint

14: Badgedecal Rear  
Missing  
Replace



15: Door osr  
Scratched  
Over 25mm Not Thru Paint

16: Door osr  
Dented  
Between 10mm + 30mm



17: Door nsr  
Dented  
Between 10mm + 30mm

18: Bumper Rear  
Scratched  
Over 25mm Not Thru Paint



19: Qtr Panel osr  
Dented  
Between 10mm + 30mm

20: Qtr Panel osr  
Dented  
Between 10mm + 30mm



21: Sill os  
Dented  
With Paint Damage

22: Door osf  
Scratched  
Over 25mm Not Thru Paint



23: Seat Base Cover osf  
Holed  
Over 3mm

**Interior**

| Carpet Condition         | Average | Upholstery Condition                           | Average |
|--------------------------|---------|--|---------|
| Seat Condition           | Average | Odour  | No      |
| Engine Runs              | OK      | Gearbox 1st and Reverse Test                   | Fault   |
| Brakes                   | OK      | Clutch Slip Test from Static                   | OK      |
| Parking Brake            | OK      | Gearbox Static Gear Selection (engine running) | OK      |
|                          |         | No Excessive Smoking                           | OK      |
| EML light illuminated    | Fault   | Oil warning light illuminated                  | OK      |
| Airbag light illuminated | Fault   | DPF light illuminated                          | OK      |
| ABS light illuminated    | OK      | Service indicator light illuminated            | OK      |