



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

YH20LRJ

Ford Transit Connect 240 1.5 ECOBLUE 100PS

| Inspection | | Vehicle | |
|-----------------|----|---------|-----------|
| Serious Damage? | No | VAT | Plus VAT |
| | | V5 | To Follow |

| Details | | | | | |
|-----------|---------------------------|-------------|-------------------|-----------|-----------|
| Reg. date | 25/03/2020 | VIN | WF0SXXWPGSLB01140 | CAP Below | £4,450.00 |
| Year | 2020 | Body Style | Panel Van L2 | Gearbox | MANUAL |
| Mileage | 62,234 Miles Warranted | MOT Due | 12/02/2027 | Gears | 6 |
| Fuel Type | Diesel | CAP Clean | £6,350.00 | | |
| Colour | WHITE | CAP Average | £5,575.00 | | |

AD-BLUE, TWIN LOADING DOORS, E/MIRRORS



| | |
|-------|--|
| Tyres | |
| NSF | |
| NSR | |
| OSF | |
| OSR | |
| Spare | |

Features


- Front parking sensor
- Front electric windows
- Park assist camera
- Rear parking sensor
- Air conditioning

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Screen Front
Chipped
Up To 10mm



3: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm

4: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



5: Wing nsf
Dented
With Paint Damage

6: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



7: Qtr Panel osr
Dented
With Paint Damage

8: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm

Interior

| | | | |
|--------------------------|----|--|----|
| Carpet Condition | OK | Upholstery Condition | OK |
| Seat Condition | OK | Odour | No |
| Engine Runs | OK | Gearbox 1st and Reverse Test | OK |
| Brakes | OK | Clutch Slip Test from Static | OK |
| Parking Brake | OK | Gearbox Static Gear Selection (engine running) | OK |
| | | No Excessive Smoking | OK |
| EML light illuminated | OK | Oil warning light illuminated | OK |
| Airbag light illuminated | OK | DPF light illuminated | OK |
| ABS light illuminated | OK | Service indicator light illuminated | OK |