



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

DA62PKY

MERCEDES-BENZ ACTROS 1842

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present

Details					
Reg. date	24/01/2013	Colour	WHITE	Cab Type	STREAMSPACE CAB (2.3M, FLAT FLOOR)
Year	2013	VIN	WDB9634032L725084	Gearbox	AUTOMATIC
Mileage	1,665,326 Km Warranted	Body Style	Tractor Unit	Axle Combi	4x2
Fuel Type	Diesel	MOT Due	31/08/2026	Rear Suspension	Air

SLIDING 5TH WHEEL


Tyres				
NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Bluetooth connection
- Air conditioning
- Cruise control
- Front electric windows
- Digital radio
- Central locking
- Radio/CD
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Panel Front
Scratched
Over 25mm Thru Paint



2: Bonnet
Chipped
Multiple Chips



3: Panel Front
Scratched
Over 25mm Thru Paint

4: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



5: Bumper Front Moulding
Broken
Replace

6: Door nsf
Scratched
Over 25mm Thru Paint



7: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm


8: Door nsf
Chipped
Multiple Chips



9: Qtr Panel nsr
Chipped
Multiple Chips



10: Qtr Panel Trim ns
Scuffed
Over 25mm




11: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm



12: Panel Rear
Dented
With Paint Damage



13: Qtr Panel Moulding os
Broken
Replace



14: Door osf
Dented
With Paint Damage





15: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm

16: Door osf
Scratched
Over 25mm Thru Paint



17: Screen Front
Chipped
Over 10mm

Interior

Carpet Condition
Seat Condition

OK
OK

Upholstery Condition
Odour

OK
-

Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		