

VEHICLE INSPECTION REPORT

BX59DFE

DAF LF 45.160

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 24/12/2009

Year 2009

Mileage 331,708 Km Warranted

Fuel Type Diesel

Colour WHITE

VIN XLRAE45FF0L354121

Body Style Box Van

MOT Due 30/04/2026

Cab Type DAY CAB

Gearbox MANUAL

Axle Combi 4x2


Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Photos



Condition Check



Damage Photos



1: Bumper Front
Rusted
Over 5mm



2: Bonnet
Cracked
Replace



3: Panel Front
Cracked
Replace



4: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



5: Qtr Panel osr
Cracked
Replace



6: Door osf
Scratched
Over 25mm Not Thru Paint



7: Carpets Front
Torn
Over 10mm



8: Seat Base Cover osf
Holed
Over 3mm

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK	
Brakes	OK		Clutch Slip Test from Static	OK	
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK	
			No Excessive Smoking	OK	
EML light illuminated	OK		Oil warning light illuminated	OK	
Airbag light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	OK		Service indicator light illuminated	OK	