



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

DG68MWX

Isuzu D-Max 1.9

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT
V5 Present

Details

| | | | | | |
|-----------|---------------------------|-------------|-------------------|------------|-----------|
| Reg. date | 24/10/2018 | VIN | MPATFS87JJT006427 | CAP Below | £4,750.00 |
| Year | 2018 | Body Style | Pickup Single Cab | Gearbox | MANUAL |
| Mileage | 72,949 Miles Warranted | MOT Due | 23/10/2026 | Gears | 6 |
| Fuel Type | Diesel | CAP Clean | £7,400.00 | Axle Combi | 4x4 |
| Colour | WHITE | CAP Average | £6,250.00 | | |

TOW BAR

Tyres

NSF

NSR

OSF


OSR

Spare

Features


- Air conditioning
- Front electric windows

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Screen Front
Chipped
UpTo 10mm



3: Bumper Front Moulding
Broken
Replace

4: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



5: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm

6: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm



7: Qtr Panel nsr
Cracked
Replace

8: Lamp nsr
Broken
Replace



9: Qtr Panel nsr
Dented
Between 10mm + 30mm

10: Qtr Panel osr
Cracked
Replace



11: Qtr Panel osr
Cracked
Replace

12: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm



13: Seat Base Cover osf
Holed
Over 3mm

Interior

| Carpet Condition | Average | Upholstery Condition | Average |
|--------------------------|---------|--|---------|
| Seat Condition | Average | Odour | No |
| Engine Runs | OK | Gearbox 1st and Reverse Test | OK |
| Brakes | OK | Clutch Slip Test from Static | OK |
| Parking Brake | OK | Gearbox Static Gear Selection (engine running) | OK |
| | | No Excessive Smoking | OK |
| EML light illuminated | OK | Oil warning light illuminated | OK |
| Airbag light illuminated | OK | DPF light illuminated | OK |
| ABS light illuminated | OK | Service indicator light illuminated | OK |