



**COMMERCIAL VEHICLE AUCTIONS LTD**  
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate  
Doncaster  
DN4 8DE

01302 732600 | [cva.noreply@cva-auctions.co.uk](mailto:cva.noreply@cva-auctions.co.uk)

# VEHICLE INSPECTION REPORT

**CK16UCL**

## Mercedes-Benz Actros

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present

Details					
Reg. date	05/07/2016	VIN	WDB96342320066241	Axle Combi	6x2
Year	2016	Body Style	Tractor Unit	Steering Combi	Mid-Lift
Mileage	1,057,458 Km Not Warranted	MOT Due	31/01/2027	Rear Suspension	Air
Fuel Type	Diesel	Cab Type	STREAMSPACE CAB (2.5M, FLAT FLOOR)		
Colour	WHITE	Gearbox	AUTOMATIC		

### SLIDING 5TH WHEEL



Tyres				
NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

## Features

- Bluetooth connection
- LED headlights
- Drivers airbag
- Cruise control
- Manual sunroof
- Passenger airbag
- Digital radio
- Air conditioning
- Central locking
- Radio/CD
- Front electric windows
- Cloth seat trim


## Photos







## Condition Check



## Damage Photos



1: Bumper Front Moulding  
Broken  
Replace



2: Door osf  
Chipped  
Over 5mm



3: Door osf  
Chipped  
Edge Chip

4: Panel Front  
Cracked  
Replace



5: Moulding nsf Wing  
Scuffed (Unpainted)  
Over 100mm

6: Bumper Front Moulding  
Scuffed (Unpainted)  
Over 100mm



7: Roof  
Dented  
Over 30mm

## Interior

<b>Carpet Condition</b>	OK	<b>Upholstery Condition</b>	OK
<b>Seat Condition</b>	Average	<b>Odour</b>	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK