



**COMMERCIAL VEHICLE AUCTIONS LTD**  
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate  
Doncaster  
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

# VEHICLE INSPECTION REPORT

**AV69LUA**

## Volvo FM 330

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present

Details					
Reg. date	17/12/2019	VIN	YV2X9J0C6LB925370	Axle Combi	6x2
Year	2019	Body Style	Curtainside	Rear Suspension	Air
Mileage	581,506 Km Not Warranted	MOT Due	31/07/2026	Rear Doors	Barn
Fuel Type	Diesel	Cab Type	LXL GLOBETROTTER		
Colour	WHITE	Gearbox	AUTOMATIC		

REAR LIFT, SURROUND CAMERA SYSTEM




Tyres				
NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4


## Features

- Bluetooth connection
- Auxiliary input socket
- Air conditioning
- Central locking
- Cruise control
- Digital radio
- Front electric windows
- Cloth seat trim
- Navigation system
- LED headlights
- Drivers airbag
- Park assist camera
- Manual sunroof
- Passenger airbag


## Photos







## Condition Check



## Damage Photos



1: Door Lock osf  
Broken  
Replace

2: Panel Front  
Scratched  
Over 25mm Not Thru Paint



3: Door osf  
Chipped  
Multiple Chips

4: Panel Front  
Chipped  
Over 5mm



5: Screen Front  
Chipped  
UpTo 10mm

6: Screen Front  
Chipped  
UpTo 10mm

### Interior

#### Carpet Condition Seat Condition

Average  
Average

#### Upholstery Condition Odour

Average  
-

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK

Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		