



**COMMERCIAL VEHICLE AUCTIONS LTD**  
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate  
Doncaster  
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

# VEHICLE INSPECTION REPORT

**RA19GGZ**

## Fiat Doblo 1.4 CARGO

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT  
V5 Present

### Details

Reg. date	03/05/2019	VIN	ZFA26300006N01999	CAP Below	£975.00
Year	2019	Body Style	Panel Van L1	Gearbox	MANUAL
Mileage	70,217 Miles Not Warranted	MOT Due	28/07/2026	Gears	5
Fuel Type	Petrol	CAP Clean	£1,450.00		
Colour	WHITE	CAP Average	£1,225.00		

V60 SLIP PRESENT, TWIN LOADING DOOR, E/MIRRORS


### Tyres

NSF
NSR
OSF
OSR
Spare

## Features


- Rear parking sensor
- Air conditioning
- Front electric windows

## Photos





## Condition Check



## Damage Photos



1: Wing of  
Scratched  
Over 25mm Not Thru Paint



2: Bonnet  
Chipped  
Multiple Chips



3: Door Mirror Assy nsf  
Scratched (Painted)  
Over 25mm Not Thru Paint

4: Door Mirror Glass ns  
Broken  
Replace



5: Qtr Panel nsr  
Scratched  
Over 25mm Not Thru Paint

6: Door nsr  
Poor Previous Repair  
Poor Colour



7: Door osr  
Dented  
With Paint Damage

8: Door nsr  
Dented  
Over 30mm



9: Door nsr  
Dented  
Over 30mm

10: Qtr Panel osr  
Dented  
With Paint Damage



11: Qtr Panel osr  
Dented  
Over 30mm

12: Door osf  
Scratched  
Up To 25mm Not Thru Paint



13: Door Mirror Assy osf  
Scratched (Painted)  
Over 25mm Thru Paint

14: Screen Front  
Chipped  
Up To 10mm

**Interior**

<b>Carpet Condition</b>	Average	<b>Upholstery Condition</b>	Average
<b>Seat Condition</b>	Average	<b>Odour</b>	No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK